Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC. **Well Operator:** XTO ENERGY INC.

Well Name: MEYER 24X-22B

Field Name: MIDWAY Well File #: 23241

Date Incident:9/11/2014Time Incident:09:30Facility ID Number:County:WILLIAMSTwp: 157Rng: 96Sec: 22Qtr:

Location Description:

Submitted By: Kaylan Dirkx Received By:

Contact Person: Kaylan Dirkx

P.O Box 1589 Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
20 Barrels 17 Barrels 17 barrels

Oil Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/19/2015 Clean Up Concluded: 9/25/2014

Risk Evaluation:

None- the majority of the spill was contained within the lined metal berm. A light mist blew outside of the berm but remained on location.

Areal Extent:

Potential Environmental Impacts:

None- the majority of the spill was contained within the lined metal berm. A light mist blew outside of the berm but remained on location. A vac truck recovered the majority of the oil.

Action Taken or Planned:

A vac truck recovered 17 bbls of oil and returned the fluid to the production tanks. Any impacted material will be removed and hauled to an approved facility.

Wastes Disposal Location: Recovered liquids were returned to the production tanks. Impacted soil will be disposed at Indian Hills Disposal.

Agencies Involved:

Updates

Date: 9/12/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.